#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-011429 Address: 333 Burma Road **Date Inspected:** 29-Dec-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

**Bridge No:** 34-0006 **Component:** OBG

#### **Summary of Items Observed:**

This CALTRANS OSM Quality Assurance Inspector (QA) was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

#### ULTRASONIC TESTING(UT)

This QA performed 10% verification Ultrasonic Testing (UT) for OBG segment 8CW, T,Butt & Corner joints.

This weld was previously tested and accepted by ZPMC Quality Control (QC) UT technicians.

The weld designations reviewed are as follows:

SEG047-011,012,036,045,046,048.

SEG047B-017,018,019,015,016,009,010,014,006,007,008.

SEG047J-048,039,041,042,043.

The following welds did not comply with the applicable contract document.

SEG047B-012,013.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents

### **Summary of Conversations:**

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Relevant conversation noted.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Prabhu,Surendra	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer